must be performed. The CumSum statistic recalculation must not indicate that the family has exceeded the action limit for two consecutive tests. Where applicable, the manufacturer's final credit report as required by §90.210 must break out the credits that result from each FEL and corresponding CumSum analysis for the set of engines built to each FEL.

§ 90.709 Calculation and reporting of test results.

- (a) Initial test results are calculated following the applicable test procedure specified in §90.707 (a). The manufacturer rounds these results to the number of decimal places contained in the applicable emission standard expressed to one additional significant figure.
- (b) Final test results are calculated by summing the initial test results derived in paragraph (a) of this section for each test engine, dividing by the number of tests conducted on the engine, and rounding to the same number of decimal places contained in the applicable standard expressed to one additional significant figure.
- (c) The final deteriorated test results for each test engine are calculated by applying the appropriate deterioration factors, derived in the certification process for the engine to the final test results, and rounding to the same number of decimal places contained in the applicable standard.
- (d) If, at any time during the model year, the CumSum statistic exceeds the applicable action limit, H, in two consecutive tests for any regulated pollutant, (HC+NO_X (NMHC+NO_X) or CO) the engine family may be determined to be in noncompliance and the manufacturer must notify EPA by contacting its official EPA certification representative within ten working days of such exceedance by the CumSum statistic.
- (e) Within 45 calendar days of the end of each quarter, each engine manufacturer must submit to the Administrator a report which includes the following information:
- (1) The location and description of the manufacturer's or other's exhaust emission test facilities which were utilized to conduct testing reported pursuant to this section:

- (2) Total production and sample sizes, N and n, for each engine family;
- (3) The FEL (standard, if no FEL) against which each engine family was tested;
- (4) A description of the process to obtain engines on a random basis;
- (5) A description of the test engines;
- (6) For each test conducted:
- (i) A description of the test engine, including:
- (A) Configuration and engine family identification;
 - (B) Year, make, and build date;
- (C) Engine identification number; and
- (D) Number of hours of service accumulated on engine prior to testing;
- (ii) Location where service accumulation was conducted and description of accumulation procedure and schedule;
- (iii) Test number, date, test procedure used, initial test results before and after rounding, final test results before and after rounding and final deteriorated test results for all exhaust emission tests, whether valid or invalid, and the reason for invalidation, if applicable;
- (iv) A complete description of any adjustment, modification, repair, preparation, maintenance, and/or testing which was performed on the test engine, was not reported pursuant to any other paragraph of this subpart, and will not be performed on all other production engines:
- (v) A CumSum analysis, as required in §90.708, of the production line test results for each engine family; and
- (vi) Any other information the Administrator may request relevant to the determination whether the new engines being manufactured by the manufacturer do in fact conform with the regulations with respect to which the certificate of conformity was issued;
- (7) For each failed engine as defined in §90.710(a), a description of the remedy and test results for all retests as required by §90.711(g);
- (8) The date of the end of the engine manufacturer's model year production for each engine family; and
- (9) The following signed statement and endorsement by an authorized representative of the manufacturer:

This report is submitted pursuant to Sections 213 and 208 of the Clean Air Act. This

§ 90.710

production line testing program was conducted in complete conformance with all applicable regulations under 40 CFR Part 90. No emission-related changes to production processes or quality control procedures for the engine family tested have been made during this production line testing program that affect engines from the production line. All data and information reported herein is, to the best of (Company Name) knowledge, true and accurate. I am aware of the penalties associated with violations of the Clean Air Act and the regulations thereunder. (Authorized Company Representative.)

§ 90.710 Compliance with criteria for production line testing.

- (a) A failed engine is one whose final deteriorated test results pursuant to $\S 90.709(c)$, for $HC+NO_X$ (NMHC+NO_X) or CO exceeds the applicable Family Emission Limit (FEL) or standard if no FEL.
- (b) An engine family shall be determined to be in noncompliance, if at any time throughout the model year, the CumSum statistic, $C_{\rm i}$, for HC+NO_X (NMHC+NO_X) or CO, is greater than the action limit, H, for that pollutant, for two consecutive tests.

§ 90.711 Suspension and revocation of certificates of conformity.

- (a) The certificate of conformity is suspended with respect to any engine failing pursuant to §90.710(a) effective from the time that testing of that engine is completed.
- (b) The Administrator may suspend the certificate of conformity for an engine family which is determined to be pursuant noncompliance §90.710(b). This suspension will not occur before thirty days after the engine family is determined to be in noncompliance and the Administrator has notified the manufacturer of its intent to suspend. During this thirty day period the Administrator will work with the manufacturer to achieve appropriate production line changes to avoid the need to halt engine production, if possible. The Administrator will approve or disapprove any such production line changes proposed to address a family that has been determined to be in noncompliance under this subpart within 15 days of receipt. If the Administrator does not approve or disapprove such a proposed change within such

time period, the proposed change shall be considered approved.

- (c) If the results of testing pursuant to the regulations in this subpart indicate that engines of a particular family produced at one plant of a manufacturer do not conform to the regulations in this part with respect to which the certificate of conformity was issued, the Administrator may suspend the certificate of conformity with respect to that family for engines manufactured by the manufacturer at all other plants.
- (d) Notwithstanding the fact that engines described in the application for certification may be covered by a certificate of conformity, the Administrator may suspend such certificate immediately in whole or in part if the Administrator finds any one of the following infractions to be substantial:
- (1) The manufacturer refuses to comply with any of the requirements of this subpart.
- (2) The manufacturer submits false or incomplete information in any report or information provided to the Administrator under this subpart.
- (3) The manufacturer renders inaccurate any test data submitted under this subpart.
- (4) An EPA enforcement officer is denied the opportunity to conduct activities authorized in this subpart and a warrant or court order is presented to the manufacturer or the party in charge of the facility in question.
- (5) An EPA enforcement officer is unable to conduct activities authorized in §90.705 because a manufacturer has located its facility in a foreign jurisdiction where local law prohibits those activities.
- (e) The Administrator shall notify the manufacturer in writing of any suspension or revocation of a certificate of conformity in whole or in part, except that the certificate is immediately suspended with respect to any failed engines as provided for in paragraph (a) of this section.
- (f) The Administrator may revoke a certificate of conformity for an engine family after the certificate has been suspended pursuant to paragraph (b) or (c) of this section if the proposed remedy for the nonconformity, as reported